No. TCD-8379A-1-2015

Date of Issue: February 27, 2015

Japan Civil Aviation Bureau

TAIKUSEI-KAIZEN-TSUHO

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

- 1. Applies to: Kawasaki BK117 C-2 helicopters
- 2. Compliance is required as indicated, unless already accomplished.
 - To prevent the detachment of a person or external load from the helicopter hoist, due to an incorrect installation of retaining ring inside the damper unit, accomplish the following.
- 2.1 For helicopters equipped with the Goodrich hook damper on the rescue winch system, Part Number (P/N) 44307-480 or P/N 44307-480-1, before the next hoist operation after February 11, 2015 (the effective date of TCD-8379A-2015), accomplish the action as specified in paragraph 2.1.1, 2.1.2, 2.1.3 or 2.1.4 in accordance with the instructions of Kawasaki Service Bulletin No. KSB-117-372C dated February 5, 2015, or No. KSB-117-372D dated February 26, 2015, or later JCAB-approved revision.
 - 2.1.1 Deactivate the rescue winch system.
- 2.1.2 Replace the hook damper with a serviceable part.
- 2.1.3 Remove the rescue winch system from the helicopter.
- 2.1.4 Modify the hook damper by replacing a split retainer P/N 42305-286 with a single-piece retainer P/N B851M2060201.
- 2.2 From February 11, 2015 (the effective date of TCD-8379A-2015), it is allowed to install a hook damper having P/N 44307-480 or P/N 44307-480-1, and a rescue winch system incorporating a hook damper having P/N 44307-480 or P/N 44307-480-1, provided that the hook damper is equipped with a single-piece retainer P/N B851M2060201.
- 2.3 An alternative means of compliance with this AD may be used, if approved by the Director-General of JCAB.

This is the English translation. In case of any difficulty, refer to the Japanese original text.