August 28, 2009

Aircraft Accident - B18616 (Boeing 737-800) Operated by China Airlines Occurred at Naha Airport on Aug. 20, 2007

The Japan Transport Safety Board recommends the Federal Aviation Administration of the United States of America to supervise the Boeing Company, the manufacturer of the Aircraft, to take the following actions:

When preparing maintenance job instructions for airlines such as Service Letters/Bulletins, the scopes of jobs should be clearly defined and the working conditions and environments including accessibilities to job areas should be appropriately evaluated in order to prevent maintenance errors.