

KOKU-KU-KI-869

No. TCD-9687-2020

Date of Issue: December 25, 2020

Japan Civil Aviation Bureau

TAIKUSEI-KAIZEN-TSUHO

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: Kawasaki BK117, BK117 A-3, BK117 A-4, BK117 B-1, BK117 B-2, BK117 C-1 and BK117 C-2 helicopters.

2. Compliance is required as indicated, unless already accomplished.

To comply with Airworthiness Limitation Section of the Instruction for Continued Airworthiness, accomplish the following.

Note 1 : For the purpose of this AD, an affected part is the part listed in Table 1 to Table 3 of Kawasaki Service Bulletin No. KSB-117-462 or any further JCAB-approved revision (hereinafter referred to as SB).

2.1 Within 4 weeks after the effective date of this AD, modify the descriptions of time change items in the Aircraft Logbook or the history logs in accordance with the instructions of paragraph 9.(1) of SB.

2.2 An alternative means of compliance with this AD may be used, if approved by the Director-General of JCAB.

3. Remarks

3.1 This AD becomes effective on January 8, 2020.

3.2 Kawasaki Service Bulletin No. KSB-117-462 dated November 13, 2020 and later JCAB approved revisions pertain to this subject.